

## View Damage Code Detail

[Help](#)

|                             |                                       |
|-----------------------------|---------------------------------------|
| <b>Repair Order Number</b>  | 372025                                |
| <b>Dealer</b>               | 1414                                  |
| <b>Repair Date</b>          | 10/05/06                              |
| <b>Customer Name</b>        | Adolf Hermann                         |
| <b>Warranty Mileage</b>     |                                       |
| <b>Vehicle ID Number</b>    | WP0CB29964S676144                     |
| <b>Model</b>                | 2004 996 620 2004 911 Turbo Cabriolet |
| <b>Warranty Code</b>        | 2 New Car Wty                         |
| <b>Damage Code</b>          | 9687 040 000 2                        |
| <b>Audit Trail</b>          | 200642                                |
| <b>Dealer Line</b>          | 5                                     |
| <b>Part ID Desc.</b>        | Control unit f alarm system           |
| <b>Edit Cycle</b>           | 01                                    |
| <b>Reason Code</b>          | electrical                            |
| <b>Adjustment Code</b>      |                                       |
| <b>Manufacturer Desc.</b>   | Vendor Not Req.                       |
| <b>Authorization Code</b>   |                                       |
| <b>Repair/Replace Desc.</b> | New part used                         |
| <b>Claim Category</b>       | 1                                     |
| <b>Service Advisor</b>      | KELLEY                                |

|         |  |
|---------|--|
| C MPLNT | TECH NOTED ALARM BOX SHORTED WHILE TRYING TO PROGRAM CUSTOMERS |
| C MPLNT | NEW REMOTES  |
| CAUSE   | ALARM BOX WOULD NOT ALLOW ACCESS TO ANY OF THE SYSTEM.         |
| CAUSE   | INTERNAL SHORT. PERFORMED VEHICLE ANALYSIS & PRINTED REPORT    |
| CORREC  | R R DRIVERS SEAT, REPLACED ALARM CONTROL UNIT AND PROGRAMMED   |

[Back](#)