

Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

Phones listed below have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

| Phone Manufacturer | Phone Model | Type | Phonebook Download ³ | Minimum Firmware ⁴ | First Model Year |
|-------------------------------------|-------------------------|------|------------------------------------|-------------------------------|------------------------|
| Alltel | | | | | |
| LG | AX830 Glimmer | CDMA | Yes | T83ATV05 | 2008 |
| | AX300 | CDMA | Yes | T30ATV03 | 2008 |
| | AX355 | CDMA | No | T35ATV01 | 2007 |
| | AX8600 | CDMA | Yes | T86ATV06 | 2007 |
| Motorola | Z6m | CDMA | Yes ⁸ | 02.0C.19P | 2008 |
| | V9m | CDMA | Yes ⁸ | 02.0C.19A | 2008 |
| | Q | CDMA | Yes | 06.0C.0EP | 2007 |
| | E815 | CDMA | Yes | 8720_01.17.03 | 2007 |
| Palm | Treo 755p | CDMA | "Favorites" only | 1.02-CDMA | 2008 |
| | Treo 700p | CDMA | "Favorites" only | 1.42/32/142 | 2007 |
| | Treo 700wx | CDMA | "Favorites" only | 1.11-ROWEN | 2007 |
| Research In Motion (RIM) | BlackBerry 7130e | CDMA | No | V4.1 | 2007 |
| | BlackBerry 8703e | CDMA | No | v4.10.373 | 2007 |
| Samsung | u706 Muse | CDMA | Yes | BC04 | 2008 |
| | R430 | CDMA | Yes | BE17 | 2008 |
| | R500 | CDMA | Yes | AF16 | 2008 |
| AT&T | | | | | |
| Apple | iPhone ⁹ | GSM | Yes | 1.1.4 | 2007 |
| HTC | Tilt 8925 | GSM | Yes | 1.57 | 2008 |
| Motorola | Q9h | GSM | Yes ⁸ | 40.11.0FR | 2008 |
| | KRZR | GSM | Yes | 08.42.0BR_B | 2008 |
| | V3 RAZR | GSM | Yes | 41.C3R | 2006 |
| | V3i | GSM | Yes | 08.D8.35R | 2007 |
| | V3xx | GSM | Yes | 96.71.95R | 2007 |
| | SLVR | GSM | Yes | 08.C4.1ER | 2007 |
| | V620 | GSM | Yes | G_0E.65.25R | 2005 ⁷ |
| | V600 | GSM | Yes | G_0B.09.2FR | 2005 ⁷ |
| | V557 | GSM | Yes | G_08.28.3DR | 2007 |
| | V551 | GSM | Yes | G_08.17.0FR | 2005 ⁷ |
| | V540 | GSM | Yes | G_08.18.40R | 2007 |
| | V505 | GSM | Yes | G_0B.09.4AR | 2005 ⁷ |
| | V500 | GSM | Yes | G_0B.09.17R | 2005 ⁷ |
| | V400 ¹ | GSM | Yes | G_0B.09.2FR_A1 | 2005 ⁷ |
| V300 ¹ | GSM | Yes | G_0B.09.3AR_A | 2005 ⁷ | |
| V60 ^{1,2} | all | Yes | - | 2005 | |
| Nokia | 6555 | GSM | Yes | V 03.31 | 2008 |
| | 6820 | GSM | No | V04.46 | 2005 |
| | 6230 | GSM | Yes | V05.24 | 2005 ⁶ |
| Palm | Centro - 685 | GSM | Yes | G.R01.12 | 2008 |
| | Treo 650 | GSM | "Favorites" only | 1.13 ⁵ | 2006 |
| | Treo 680 | GSM | "Favorites" only | 1.31 | 2007 |
| Research In Motion (RIM) | BlackBerry 8100 (Pearl) | GSM | Yes ⁸ | 4.2.0.51 | 2008 |
| | BlackBerry 8300 (Curve) | GSM | Yes ⁸ | 4.2.2.30 | 2008 |
| | BlackBerry 8800 | GSM | Yes ⁸ | 4.2.1.72 | 2008 |
| | BlackBerry 7100 | GSM | No | 4.0.0.198 | 2006 |
| | BlackBerry 7290 | GSM | No | 4.0.0.198 | 2006 |
| Siemens | S56 | GSM | Yes | 20 | 2005 |
| | S66 | GSM | Yes | 48 | 2005 ⁶ |

Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

| | | | | | |
|--------------------------|---------------------|--------|------------------|----------------|-------------------|
| Sony Ericsson | Z750a | GSM | Yes | R1DB005 | 2008 |
| | W580i | GSM | Yes | R7AC001 | 2008 |
| | W300i | GSM | Yes | R4EA031 | 2007 |
| | W810i | GSM | Yes | R4EA031 | 2007 |
| | Z525i | GSM | Yes | R3K028 | 2007 |
| | T610 | GSM | Yes | R3A | 2005 ⁶ |
| | T616 | GSM | Yes | R1B | 2005 |
| | T630 | GSM | Yes | R3C | 2005 ⁶ |
| | T637 | GSM | Yes | R5A | 2006 |
| | T637 | GSM | Yes | R3A | 2005 ⁶ |
| Nextel | | | | | |
| Motorola | i335 | Nextel | No | R7F.00.02 | 2008 |
| | i880 | Nextel | No | R6E.00.01 | 2007 |
| | i870 | Nextel | No | R5B.00.04 | 2007 |
| | i580 | Nextel | No | R5C.00.01 | 2007 |
| | i605 | Nextel | No | R2F.00.00 | 2007 |
| Sprint | | | | | |
| HTC | Touch | CDMA | Yes | 2.13 | 2008 |
| | Mogul 6800 | CDMA | No | 1.32 | 2008 |
| Palm | Treo 800w | CDMA | Yes | 15117/116 | 2008 |
| | Centro - 690 | CDMA | Yes | 1081/49 | 2008 |
| | Treo 755p | CDMA | "Favorites" only | 1.04-STNT | 2008 |
| RIM | BlackBerry 8830 | CDMA | Yes ⁸ | 4.2.2.123 | 2008 |
| | BlackBerry 7130e | CDMA | No | V4.1 | 2007 |
| Samsung | M510 | CDMA | Yes | AC19 | 2007 |
| | M620 UpStage | CDMA | Yes | AC08 | 2007 |
| | M610 | CDMA | Yes | ZJ29 | 2007 |
| | A900M | CDMA | Yes | ZJ23 | 2007 |
| | M500 | CDMA | Yes | ZK03 | 2007 |
| | A960 | CDMA | Yes | ZA09 | 2007 |
| | A900 | CDMA | Yes | ZD12 | 2007 |
| | A940 | CDMA | Yes | ZA13 | 2007 |
| | U420 | CDMA | No | ZF29 | 2007 |
| Sanyo | SCP-3800 Katana LX | CDMA | Yes | 1.002SP | 2008 |
| | SCP-8500 Katana DLX | CDMA | Yes | 1.002SP | 2008 |
| | SCP-6600 Katana | CDMA | Yes | 1.000SP | 2007 |
| | SCP-8400 | CDMA | Yes | 1.002SP | 2007 |
| | SCP-7050 | CDMA | Yes | 1.002SP | 2007 |
| | M1 | CDMA | Yes | 1.001SP | 2007 |
| Motorola | V60 ^{1,2} | all | Yes | - | 2005 |
| T-Mobile | | | | | |
| Motorola | V3 RAZR | GSM | Yes | 42.09R | 2006 |
| | Pebl | GSM | Yes | 08.84.2AR_A | 2007 |
| | V620 | GSM | Yes | G_0E.65.25R | 2005 ⁷ |
| | V600 | GSM | Yes | G_0B.09.2FR | 2005 ⁷ |
| | V557 | GSM | Yes | G_08.28.3DR | 2007 |
| | V551 | GSM | Yes | G_08.17.0FR | 2005 ⁷ |
| | V540 | GSM | Yes | G_08.18.40R | 2007 |
| | V505 | GSM | Yes | G_0B.09.4AR | 2005 ⁷ |
| | V500 | GSM | Yes | G_0B.09.17R | 2005 ⁷ |
| | V400 ¹ | GSM | Yes | G_0B.09.2FR_A1 | 2005 ⁷ |
| | V300 ¹ | GSM | Yes | G_0B.09.3AR_A | 2005 ⁷ |
| | Nokia | 3555 | GSM | Yes | V 05.07 |

Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

| | | | | | |
|---------------------------------|-------------------------|------|------------------|---------------|-------------------|
| Research In Motion (RIM) | BlackBerry 8100 (Pearl) | GSM | Yes | 4.2.1.107 | 2008 |
| | BlackBerry 8300 (Curve) | GSM | Yes | 4.2.2.180 | 2008 |
| | BlackBerry 8800 | GSM | Yes | 4.2.1.74 | 2008 |
| | BlackBerry 7100 | GSM | No | 4.0.0.198 | 2006 |
| | BlackBerry 7290 | GSM | No | 4.0.0.198 | 2006 |
| Sony Ericsson | T610 | GSM | Yes | R3A | 2005 ⁶ |
| Verizon | | | | | |
| LG | VX9100 enV2 | CDMA | Yes | VX910V03 | 2008 |
| | VX8550 Chocolate | CDMA | Yes | VX855V01 | 2008 |
| | VX8600 | CDMA | Yes | T86VZV02 | 2007 |
| | VX8700 | CDMA | Yes | T87VZB02 | 2007 |
| | VX9400 | CDMA | Yes | T94VZB01 | 2007 |
| | VX8100 | CDMA | No | T81VZ07 | 2007 |
| | VX8300 | CDMA | Yes | T83VZV02 | 2007 |
| | VX8500 Chocolate | CDMA | Yes | T85VZB02 | 2007 |
| Motorola | Q9c | CDMA | Yes ⁸ | 04.08.20-34P | 2008 |
| | Q9m | CDMA | Yes ⁸ | 03.20.0EP | 2008 |
| | V9m | CDMA | Yes ⁸ | 01.15.0D | 2008 |
| | Z6c | CDMA | Yes ⁸ | 01.30.11P | 2008 |
| | V325i | CDMA | Yes ⁸ | 01.07.00R | 2008 |
| | W385 | CDMA | Yes ⁸ | 00.18.08P | 2008 |
| | Q | CDMA | Yes | 02.07.55-13P | 2007 |
| | V3c RAZR | CDMA | Yes | 01.0F.02 | 2007 |
| | V3m | CDMA | Yes | 01.09.00 | 2007 |
| | E815 | CDMA | Yes | 8720_01.17.03 | 2007 |
| | V710 | CDMA | Yes | 8700_01.40.0R | 2006 |
| | V60 ^{1,2} | all | Yes | - | 2005 |
| Palm | Centro - 690 | CDMA | Yes | 242/119 | 2008 |
| | 700wx | CDMA | Yes | 1.24-VZW | 2008 |
| RIM | BlackBerry 8830 | CDMA | Yes ⁸ | 4.2.2.66 | 2008 |

Major GSM carriers: AT&T and T-Mobile. Major CDMA carriers: Alltel, Sprint and Verizon.

* Older phone cradles (for vehicles equipped with Audi Telematics by OnStar®) will not function in combination with the new Audi Phone Preparation. Please use the new cradle part numbers listed on this sheet.

- These phones are not Bluetooth®-equipped, but will work with the Audi Phone Preparation in conjunction with the appropriate phone cradle.
- V60 "street" phones will not work; only Audi OEM Versions sold through an Audi dealer are compatible.
- CDMA phones: numbers stored in the phonebook are synchronized with the vehicle.
GSM phones: numbers stored in the phonebook and the SIM-card are synchronized, except where noted.
- Older phone firmware may not be fully compatible and may cause system instability; contact your phone provider to be sure the latest firmware is loaded in your phone.
- Minimum v1.15 for AT&T version. Software downloads available at www.palm.com
- MY2005 A8 models without Audi Telematics by OnStar® equipment are compatible.
MY2005 A6 models after VIN: 4F_070061 are compatible.
- Audi strongly recommends the use of the Audi phone cradle for optimum performance in MY2005 vehicles.

| Audi Phone Cradle Part Number | Supported Phone Models |
|-------------------------------|---|
| 4F0 051 435 B | Motorola V300, V400, V500, V505, V540, V551, V557, V600, V620 |
| 4F0 051 435 C | Motorola V710 |
| 4F0 051 435 D | Sony Ericsson T610, T616, T630, T637 |
| 4F0 051 435 E | Motorola V60 |

- Dialed, Missed, and Received call lists downloaded from phone are inaccurate
- For optimal audio quality disable Wi-Fi on phone. A short noise may sporadically occur when calls first initiated.
Limitations dialing International numbers from memory. Silent ringer should not be used in MY07 vehicles.

Audi of America, Inc. and Audi Canada believe the information presented to be correct at the time of publication. All specifications are subject to revision. Check the www.audiusa.com or www.audicanada.ca websites regularly for updates to this matrix. Bluetooth® is a registered trademark of the Bluetooth SIG, Inc.. OnStar® is a registered trademark of OnStar Corporation.

Rev. 7/23/2008

Audi Phone Preparation with Bluetooth®

Compatible Cell Phones by Manufacturer

Phones listed below have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

| Phone Manufacturer | Phone Model | Type | Phonebook Download ³ | Minimum Firmware ⁴ | First Model Year |
|--------------------|-----------------------|--------|---------------------------------|-------------------------------|-------------------|
| Apple | iPhone ¹³ | GSM | Yes | 1.1.4 | 2007 |
| HTC | Touch | CDMA | Yes | 2.13 | 2008 |
| | Tilt 8925 | GSM | Yes | 1.57 | 2008 |
| | Mogul 6800 | CDMA | No | 1.32 | 2008 |
| Motorola | Q9c | CDMA | Yes ¹² | 04.08.20-34P | 2008 |
| | Q9h | GSM | Yes ¹² | 40.11.0FR | 2008 |
| | Q9m | CDMA | Yes ¹² | 03.20.0EP | 2008 |
| | V9m | CDMA | Yes ¹² | See Provider list | 2008 |
| | Z6c | CDMA | Yes ¹² | 01.30.11P | 2008 |
| | Z6m | CDMA | Yes ¹² | 02.0C.19P | 2008 |
| | V325 | CDMA | Yes ¹² | 01.07.00R | 2008 |
| | W385 | CDMA | Yes ¹² | 00.18.08P | 2008 |
| | Q | CDMA | Yes | See Provider list | 2007 |
| | KRZR | GSM | Yes | 08.42.0BR_B | 2008 |
| | V3 RAZR | GSM | Yes | See Provider list | 2006 |
| | V3c RAZR | CDMA | Yes | 01.0F.02 | 2007 |
| | V3i | GSM | Yes | 08.D8.35R | 2007 |
| | V3m | CDMA | Yes | 01.09.00 | 2007 |
| | V3xx | GSM | Yes | 96.71.95R | 2007 |
| | SLVR | GSM | Yes | 08.C4.1ER | 2007 |
| | Peb1 | GSM | Yes | 08.84.2AR_A | 2007 |
| | E815 | CDMA | Yes | 8720_01.17.03 | 2007 |
| | V710 ⁹ | CDMA | Yes | 8700_01.40.0R | 2006 |
| | V620 ⁸ | GSM | Yes | G_0E.65.25R | 2005 ⁷ |
| | V600 ⁸ | GSM | Yes | G_0B.09.2FR | 2005 ⁷ |
| | V557 ⁸ | GSM | Yes | G_08.28.3DR | 2007 |
| | V551 ⁸ | GSM | Yes | G_08.17.0FR | 2005 ⁷ |
| | V540 ⁸ | GSM | Yes | G_08.18.40R | 2007 |
| | V505 ⁸ | GSM | Yes | G_0B.09.4AR | 2005 ⁷ |
| | V500 ⁸ | GSM | Yes | G_0B.09.17R | 2005 ⁷ |
| | V400 ^{1,8} | GSM | Yes | G_0B.09.2FR_A1 | 2005 ⁷ |
| | V300 ^{1,8} | GSM | Yes | G_0B.09.3AR_A | 2005 ⁷ |
| | i335 | Nextel | No | R7F.00.02 | 2008 |
| | i880 | Nextel | No | R6E.00.01 | 2007 |
| | i870 | Nextel | No | R5B.00.04 | 2007 |
| | i580 | Nextel | No | R5C.00.01 | 2007 |
| | i605 | Nextel | No | R2F.00.00 | 2007 |
| | V60 ^{1,2,11} | all | Yes | - | 2005 |
| LG | AX830 Glimmer | CDMA | Yes | T83ATV05 | 2008 |
| | AX300 | CDMA | Yes | T30ATV03 | 2008 |
| | VX9100 enV2 | CDMA | Yes | VX910V03 | 2008 |
| | VX8550 Chocolate | CDMA | Yes | VX855V01 | 2008 |
| | VX8500 Chocolate | CDMA | Yes | T85VZB02 | 2007 |
| | AX355 | CDMA | No | T35ATV01 | 2007 |
| | AX8600 | CDMA | Yes | T86ATV06 | 2007 |
| | VX8600 | CDMA | Yes | T86VZV02 | 2007 |
| | VX8700 | CDMA | Yes | T87VZB02 | 2007 |
| | VX9400 | CDMA | Yes | T94VZB01 | 2007 |
| | VX8100 | CDMA | No | T81VZ07 | 2007 |
| | VX8300 | CDMA | Yes | T83VZV02 | 2007 |

Audi Phone Preparation with Bluetooth®

Compatible Cell Phones by Manufacturer

| | | | | | |
|---------------------------|-------------------------|------|-------------------|-------------------|-------------------|
| Nokia | 3555 | GSM | Yes | V 05.07 | 2008 |
| | 6555 | GSM | Yes | V 03.31 | 2008 |
| | 6820 | GSM | No | V04.46 | 2005 |
| | 6230 | GSM | Yes | V05.24 | 2005 ⁶ |
| Palm | Treo 800w | CDMA | Yes | 15117/116 | 2008 |
| | Centro - 690 | CDMA | Yes | See Provider list | 2008 |
| | Centro - 685 | GSM | Yes | G.R01.12 | 2008 |
| | Treo 650 | GSM | "Favorites" only | 1.13 ⁵ | 2006 |
| | Treo 680 | GSM | "Favorites" only | 1.31 | 2007 |
| | Treo 755p | CDMA | "Favorites" only | See Provider list | 2008 |
| | Treo 700p | CDMA | "Favorites" only | 1.42/32/142 | 2007 |
| | Treo 700wx | CDMA | "Favorites" only | See Provider list | 2007 |
| Research In Motion | BlackBerry 8100 (Pearl) | GSM | Yes ¹² | See Provider list | 2008 |
| | BlackBerry 8300 (Curve) | GSM | Yes ¹² | See Provider list | 2008 |
| | BlackBerry 8800 | GSM | Yes ¹² | See Provider list | 2008 |
| | BlackBerry 7100 | GSM | No | 4.0.0.198 | 2006 |
| | BlackBerry 7130e | CDMA | No | V4.1 | 2007 |
| | BlackBerry 7290 | GSM | No | 4.0.0.198 | 2006 |
| | BlackBerry 8703e | CDMA | No | v4.10.373 | 2007 |
| | BlackBerry 8830 | CDMA | Yes ¹² | See Provider list | 2008 |
| Sanyo | SCP-3800 Katana LX | CDMA | Yes | 1.002SP | 2008 |
| | SCP-8500 Katana DLX | CDMA | Yes | 1.002SP | 2008 |
| | SCP-6600 Katana | CDMA | Yes | 1.000SP | 2007 |
| | SCP-8400 | CDMA | Yes | 1.002SP | 2007 |
| | SCP-7050 | CDMA | Yes | 1.002SP | 2007 |
| | M1 | CDMA | Yes | 1.001SP | 2007 |
| Samsung | u706 Muse | CDMA | Yes | BC04 | 2008 |
| | R430 | CDMA | Yes | BE17 | 2008 |
| | R500 | CDMA | Yes | AF16 | 2008 |
| | M510 | CDMA | Yes | AC19 | 2007 |
| | M620 UpStage | CDMA | Yes | AC08 | 2007 |
| | M610 | CDMA | Yes | ZJ29 | 2007 |
| | A900M | CDMA | Yes | ZJ23 | 2007 |
| | M500 | CDMA | Yes | ZK03 | 2007 |
| | A960 | CDMA | Yes | ZA09 | 2007 |
| | A900 | CDMA | Yes | ZD12 | 2007 |
| | A940 | CDMA | Yes | ZA13 | 2007 |
| | U420 | CDMA | No | ZF29 | 2007 |
| | Siemens | S56 | GSM | Yes | 20 |
| S66 | | GSM | Yes | 48 | 2005 ⁶ |
| Sony Ericsson | Z750a | GSM | Yes | R1DB005 | 2008 |
| | W580i | GSM | Yes | R7AC001 | 2008 |
| | W300i | GSM | Yes | R4EA031 | 2007 |
| | W810i | GSM | Yes | R4EA031 | 2007 |
| | Z525i | GSM | Yes | R3K028 | 2007 |
| | T610 ¹⁰ | GSM | Yes | R3A | 2005 ⁶ |
| | T616 ¹⁰ | GSM | Yes | R1B | 2005 |
| | T630 ¹⁰ | GSM | Yes | R3C | 2005 ⁶ |
| | T637 ¹⁰ | GSM | Yes | R5A | 2006 |
| | T637 ¹⁰ | GSM | Yes | R3A | 2005 ⁶ |

Audi Phone Preparation with Bluetooth®

Compatible Cell Phones by Manufacturer

Phones listed above have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

Major GSM carriers: AT&T and T-Mobile. Major CDMA carriers: Alltel, Sprint and Verizon.

* Older phone cradles (for vehicles equipped with Audi Telematics by OnStar®) will not function in combination with the new Audi Phone Preparation. Please use the new cradle part numbers listed on this sheet.

- 1 These phones are not Bluetooth®-equipped, but will work with the Audi Phone Preparation in conjunction with the appropriate phone cradle.
- 2 V60 "street" phones will not work; only Audi OEM Versions sold through an Audi dealer are compatible.
- 3 CDMA phones: numbers stored in the phonebook are synchronized with the vehicle.
GSM phones: numbers stored in the phonebook and the SIM-card are synchronized, except where noted.
- 4 Older phone firmware may not be fully compatible and may cause system instability; contact your phone provider to be sure the latest firmware is loaded in your phone.
- 5 Minimum v1.15 for AT&T version. Software downloads available at www.palm.com
- 6 MY2005 A8 models without Audi Telematics by OnStar® equipment are compatible.
MY2005 A6 models after VIN: 4F_070061 are compatible.
- 7 Audi strongly recommends the use of the Audi phone cradle for optimum performance in MY2005 vehicles.
- 8 Audi phone cradle available, part number - 4F0 051 435 B
- 9 Audi phone cradle available, part number - 4F0 051 435 C
- 10 Audi phone cradle available, part number - 4F0 051 435 D
- 11 Audi phone cradle available, part number - 4F0 051 435 E
- 12 Dialed, Missed, and Received call lists downloaded from phone are inaccurate
- 13 For optimal audio quality disable Wi-Fi on phone. A short noise may sporadically occur when calls first initiated.
Limitations dialing International numbers from memory. Silent ringer should not be used in MY07 vehicles.

Audi of America, Inc. and Audi Canada believe the information presented to be correct at the time of publication. All specifications are subject to revision. Check the www.audiusa.com or www.audicanada.ca websites regularly for updates to this matrix. Bluetooth® is a registered trademark of the Bluetooth SIG, Inc.. OnStar® is a registered trademark of OnStar Corporation.

Rev. 7/23/2008