

# Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

Phones listed below have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

| Phone Manufacturer              | Phone Model         | Type | Phonebook Download <sup>3</sup> | Minimum Firmware <sup>4</sup> | First Model Year  |
|---------------------------------|---------------------|------|---------------------------------|-------------------------------|-------------------|
| <b>Alltel</b>                   |                     |      |                                 |                               |                   |
| <b>LG</b>                       | AX355               | CDMA | No                              | T35ATV01                      | 2007              |
|                                 | AX8600              | CDMA | Yes                             | T86ATV06                      | 2007              |
| <b>Motorola</b>                 | V9m                 | CDMA | Yes <sup>8</sup>                | 02.0B.09P                     | 2008              |
|                                 | Q                   | CDMA | Yes                             | 06.0C.0EP                     | 2007              |
|                                 | E815                | CDMA | Yes                             | 8720_01.17.03                 | 2007              |
| <b>Palm</b>                     | Treo 700p           | CDMA | "Favorites" only                | 1.42/32/142                   | 2007              |
|                                 | Treo 700wx          | CDMA | "Favorites" only                | 1.11-ROWEN                    | 2007              |
| <b>Research In Motion (RIM)</b> | BlackBerry 7130e    | CDMA | No                              | V4.1                          | 2007              |
|                                 | BlackBerry 8703e    | CDMA | No                              | v4.10.373                     | 2007              |
| <b>AT&amp;T</b>                 |                     |      |                                 |                               |                   |
| <b>Apple</b>                    | iPhone <sup>9</sup> | GSM  | Yes                             | 1.0.1                         | 2007              |
| <b>Motorola</b>                 | KRZR                | GSM  | Yes                             | 08.42.0BR_B                   | 2008              |
|                                 | V3 RAZR             | GSM  | Yes                             | 41.C3R                        | 2006              |
|                                 | V3i                 | GSM  | Yes                             | 08.D8.35R                     | 2007              |
|                                 | V3xx                | GSM  | Yes                             | 96.71.95R                     | 2007              |
|                                 | SLVR                | GSM  | Yes                             | 08.C4.1ER                     | 2007              |
|                                 | V620                | GSM  | Yes                             | G_0E.65.25R                   | 2005 <sup>7</sup> |
|                                 | V600                | GSM  | Yes                             | G_0B.09.2FR                   | 2005 <sup>7</sup> |
|                                 | V557                | GSM  | Yes                             | G_08.28.3DR                   | 2007              |
|                                 | V551                | GSM  | Yes                             | G_08.17.0FR                   | 2005 <sup>7</sup> |
|                                 | V540                | GSM  | Yes                             | G_08.18.40R                   | 2007              |
|                                 | V505                | GSM  | Yes                             | G_0B.09.4AR                   | 2005 <sup>7</sup> |
|                                 | V500                | GSM  | Yes                             | G_0B.09.17R                   | 2005 <sup>7</sup> |
|                                 | V400 <sup>1</sup>   | GSM  | Yes                             | G_0B.09.2FR_A1                | 2005 <sup>7</sup> |
|                                 | V300 <sup>1</sup>   | GSM  | Yes                             | G_0B.09.3AR_A                 | 2005 <sup>7</sup> |
| V60 <sup>1,2</sup>              | all                 | Yes  | -                               | 2005                          |                   |
| <b>Nokia</b>                    | 6555                | GSM  | Yes                             | V 03.31                       | 2008              |
|                                 | 6820                | GSM  | No                              | V04.46                        | 2005              |
|                                 | 6230                | GSM  | Yes                             | V05.24                        | 2005 <sup>6</sup> |
| <b>Palm</b>                     | Treo 650            | GSM  | "Favorites" only                | 1.13 <sup>5</sup>             | 2006              |
|                                 | Treo 680            | GSM  | "Favorites" only                | 1.31                          | 2007              |
| <b>Research In Motion (RIM)</b> | BlackBerry 8100     | GSM  | Yes <sup>8</sup>                | 4.2.0.51                      | 2008              |
|                                 | BlackBerry 8300     | GSM  | Yes <sup>8</sup>                | 4.2.2.30                      | 2008              |
|                                 | BlackBerry 8800     | GSM  | Yes <sup>8</sup>                | 4.2.1.72                      | 2008              |
|                                 | BlackBerry 7100     | GSM  | No                              | 4.0.0.198                     | 2006              |
|                                 | BlackBerry 7290     | GSM  | No                              | 4.0.0.198                     | 2006              |
| <b>Siemens</b>                  | S56                 | GSM  | Yes                             | 20                            | 2005              |
|                                 | S66                 | GSM  | Yes                             | 48                            | 2005 <sup>6</sup> |
| <b>Sony Ericsson</b>            | T616                | GSM  | Yes                             | R1B                           | 2005              |
|                                 | T630                | GSM  | Yes                             | R3C                           | 2005 <sup>6</sup> |
|                                 | T637                | GSM  | Yes                             | R5A                           | 2006              |
|                                 | T637                | GSM  | Yes                             | R3A                           | 2005 <sup>6</sup> |
|                                 | W300i               | GSM  | Yes                             | R4EA031                       | 2007              |
|                                 | W810i               | GSM  | Yes                             | R4EA031                       | 2007              |
|                                 | Z525i               | GSM  | Yes                             | R3K028                        | 2007              |

## Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

| <b>Nextel</b>                   |                     |        |           |                |                   |
|---------------------------------|---------------------|--------|-----------|----------------|-------------------|
| <b>Motorola</b>                 | i880                | Nextel | No        | R6E.00.01      | 2007              |
|                                 | i870                | Nextel | No        | R5B.00.04      | 2007              |
|                                 | i580                | Nextel | No        | R5C.00.01      | 2007              |
|                                 | i605                | Nextel | No        | R2F.00.00      | 2007              |
| <b>Sprint</b>                   |                     |        |           |                |                   |
| <b>RIM</b>                      | BlackBerry 7130e    | CDMA   | No        | V4.1           | 2007              |
| <b>Samsung</b>                  | M510                | CDMA   | Yes       | AC19           | 2007              |
|                                 | M620 UpStage        | CDMA   | Yes       | AC08           | 2007              |
|                                 | M610                | CDMA   | Yes       | ZJ29           | 2007              |
|                                 | A900M               | CDMA   | Yes       | ZJ23           | 2007              |
|                                 | M500                | CDMA   | Yes       | ZK03           | 2007              |
|                                 | A960                | CDMA   | Yes       | ZA09           | 2007              |
|                                 | A900                | CDMA   | Yes       | ZD12           | 2007              |
|                                 | A940                | CDMA   | Yes       | ZA13           | 2007              |
|                                 | U420                | CDMA   | No        | ZF29           | 2007              |
| <b>Sanyo</b>                    | SCP-8500 Katana DLX | CDMA   | Yes       | 1.002SP        | 2008              |
|                                 | SCP-6600 Katana     | CDMA   | Yes       | 1.000SP        | 2007              |
|                                 | SCP-8400            | CDMA   | Yes       | 1.002SP        | 2007              |
|                                 | SCP-7050            | CDMA   | Yes       | 1.002SP        | 2007              |
|                                 | M1                  | CDMA   | Yes       | 1.001SP        | 2007              |
| <b>Motorola</b>                 | V60 <sup>1,2</sup>  | all    | Yes       | -              | 2005              |
| <b>T-Mobile</b>                 |                     |        |           |                |                   |
| <b>Motorola</b>                 | V3 RAZR             | GSM    | Yes       | 42.09R         | 2006              |
|                                 | Pebl                | GSM    | Yes       | 08.84.2AR_A    | 2007              |
|                                 | V620                | GSM    | Yes       | G_0E.65.25R    | 2005 <sup>7</sup> |
|                                 | V600                | GSM    | Yes       | G_0B.09.2FR    | 2005 <sup>7</sup> |
|                                 | V557                | GSM    | Yes       | G_08.28.3DR    | 2007              |
|                                 | V551                | GSM    | Yes       | G_08.17.0FR    | 2005 <sup>7</sup> |
|                                 | V540                | GSM    | Yes       | G_08.18.40R    | 2007              |
|                                 | V505                | GSM    | Yes       | G_0B.09.4AR    | 2005 <sup>7</sup> |
|                                 | V500                | GSM    | Yes       | G_0B.09.17R    | 2005 <sup>7</sup> |
|                                 | V400 <sup>1</sup>   | GSM    | Yes       | G_0B.09.2FR_A1 | 2005 <sup>7</sup> |
|                                 | V300 <sup>1</sup>   | GSM    | Yes       | G_0B.09.3AR_A  | 2005 <sup>7</sup> |
| <b>Research In Motion (RIM)</b> | BlackBerry 7100     | GSM    | No        | 4.0.0.198      | 2006              |
|                                 | BlackBerry 7290     | GSM    | No        | 4.0.0.198      | 2006              |
| <b>Sony Ericsson</b>            | T610                | GSM    | Yes (SIM) | R3A            | 2005 <sup>6</sup> |

# Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Service Provider

| <b>Verizon</b>  |                    |      |                  |               |      |
|-----------------|--------------------|------|------------------|---------------|------|
| <b>LG</b>       | VX8550 Chocolate   | CDMA | Yes              | VX855V01      | 2008 |
|                 | VX8600             | CDMA | Yes              | T86VZV02      | 2007 |
|                 | VX8700             | CDMA | Yes              | T87VZB03      | 2007 |
|                 | VX9400             | CDMA | Yes              | T94VZB01      | 2007 |
|                 | VX8100             | CDMA | No               | T81VZ07       | 2007 |
|                 | VX8300             | CDMA | Yes              | T83VZV02      | 2007 |
|                 | VX8500 Chocolate   | CDMA | Yes              | T85VZB02      | 2007 |
| <b>Motorola</b> | V9m                | CDMA | Yes <sup>8</sup> | 01.15.0D      | 2008 |
|                 | V325i              | CDMA | Yes <sup>8</sup> | 01.07.00R     | 2008 |
|                 | W385               | CDMA | Yes <sup>8</sup> | 00.18.08P     | 2008 |
|                 | Q                  | CDMA | Yes              | 02.07.55-13P  | 2007 |
|                 | V3c RAZR           | CDMA | Yes              | 01.0F.02      | 2007 |
|                 | V3m                | CDMA | Yes              | 01.09.00      | 2007 |
|                 | E815               | CDMA | Yes              | 8720_01.17.03 | 2007 |
|                 | V710               | CDMA | Yes              | 8700_01.40.0R | 2006 |
|                 | V60 <sup>1,2</sup> | all  | Yes              | -             | 2005 |
| <b>RIM</b>      | BlackBerry 8830    | CDMA | Yes <sup>8</sup> | 4.2.2.66      | 2008 |

**Major GSM carriers: AT&T and T-Mobile. Major CDMA carriers: Alltel, Sprint and Verizon.**

\* Older phone cradles (for vehicles equipped with Audi Telematics by OnStar®) will not function in combination with the new Audi Phone Preparation. Please use the new cradle part numbers listed on this sheet.

- 1 These phones are not Bluetooth®-equipped, but will work with the Audi Phone Preparation in conjunction with the appropriate phone cradle.
- 2 V60 "street" phones will not work; only Audi OEM Versions sold through an Audi dealer are compatible.
- 3 CDMA phones: numbers stored in the phonebook are synchronized with the vehicle.  
GSM phones: numbers stored in the phonebook and the SIM-card are synchronized, except where noted.
- 4 Older phone firmware may not be fully compatible and may cause system instability; contact your phone provider to be sure the latest firmware is loaded in your phone.
- 5 Minimum v1.15 for AT&T version. Software downloads available at [www.palm.com](http://www.palm.com)
- 6 MY2005 A8 models without Audi Telematics by OnStar® equipment are compatible.  
MY2005 A6 models after VIN: 4F\_070061 are compatible.
- 7 Audi strongly recommends the use of the Audi phone cradle for optimum performance in MY2005 vehicles.

| Audi Phone Cradle Part Number | Supported Phone Models  |
|-------------------------------|---|
| 4F0 051 435 B                 | Motorola V300, V400, V500, V505, V540, V551, V557, V600, V620 |
| 4F0 051 435 C                 | Motorola V710   |
| 4F0 051 435 D                 | Sony Ericsson T610, T616, T630, T637                          |
| 4F0 051 435 E                 | Motorola V60  |

- 8 Dialed, Missed, and Received call lists downloaded from phone are inaccurate
- 9 A sporadic Bluetooth link disconnect may be experienced on some vehicles.  
For optimal audio quality disable Wi-Fi on phone. A short noise may sporadically occur when calls first initiated.  
Limitations dialing International numbers from memory. Silent ringer should not be used in MY07 vehicles.

Audi of America, Inc. and Audi Canada believe the information presented to be correct at the time of publication. All specifications are subject to revision. Check the [www.audiusa.com](http://www.audiusa.com) or [www.audicanada.ca](http://www.audicanada.ca) websites regularly for updates to this matrix. Bluetooth® is a registered trademark of the Bluetooth SIG, Inc.. OnStar® is a registered trademark of OnStar Corporation.

Rev. 10/15/2007

## Audi Phone Preparation with Bluetooth<sup>®</sup> Compatible Cell Phones by Manufacturer

Phones listed below have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth<sup>®</sup>-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

| Phone Manufacturer | Phone Model           | Type   | Phonebook Download <sup>3</sup> | Minimum Firmware <sup>4</sup> | First Model Year  |
|--------------------|-----------------------|--------|---------------------------------|-------------------------------|-------------------|
| <b>Apple</b>       | iPhone <sup>13</sup>  | GSM    | Yes                             | 1.0.1                         | 2007              |
| <b>Motorola</b>    | V9m                   | CDMA   | Yes <sup>12</sup>               | See Provider list             | 2008              |
|                    | V325                  | CDMA   | Yes <sup>12</sup>               | 01.07.00R                     | 2008              |
|                    | W385                  | CDMA   | Yes <sup>12</sup>               | 00.18.08P                     | 2008              |
|                    | Q                     | CDMA   | Yes                             | See Provider list             | 2007              |
|                    | KRZR                  | GSM    | Yes                             | 08.42.0BR_B                   | 2008              |
|                    | V3 RAZR               | GSM    | Yes                             | See Provider list             | 2006              |
|                    | V3c RAZR              | CDMA   | Yes                             | 01.0F.02                      | 2007              |
|                    | V3i                   | GSM    | Yes                             | 08.D8.35R                     | 2007              |
|                    | V3m                   | CDMA   | Yes                             | 01.09.00                      | 2007              |
|                    | V3xx                  | GSM    | Yes                             | 96.71.95R                     | 2007              |
|                    | SLVR                  | GSM    | Yes                             | 08.C4.1ER                     | 2007              |
|                    | Pebl                  | GSM    | Yes                             | 08.84.2AR_A                   | 2007              |
|                    | E815                  | CDMA   | Yes                             | 8720_01.17.03                 | 2007              |
|                    | V710 <sup>9</sup>     | CDMA   | Yes                             | 8700_01.40.0R                 | 2006              |
|                    | V620 <sup>8</sup>     | GSM    | Yes                             | G_0E.65.25R                   | 2005 <sup>7</sup> |
|                    | V600 <sup>8</sup>     | GSM    | Yes                             | G_0B.09.2FR                   | 2005 <sup>7</sup> |
|                    | V557 <sup>8</sup>     | GSM    | Yes                             | G_08.28.3DR                   | 2007              |
|                    | V551 <sup>8</sup>     | GSM    | Yes                             | G_08.17.0FR                   | 2005 <sup>7</sup> |
|                    | V540 <sup>8</sup>     | GSM    | Yes                             | G_08.18.40R                   | 2007              |
|                    | V505 <sup>8</sup>     | GSM    | Yes                             | G_0B.09.4AR                   | 2005 <sup>7</sup> |
|                    | V500 <sup>8</sup>     | GSM    | Yes                             | G_0B.09.17R                   | 2005 <sup>7</sup> |
|                    | V400 <sup>1,8</sup>   | GSM    | Yes                             | G_0B.09.2FR_A1                | 2005 <sup>7</sup> |
|                    | V300 <sup>1,8</sup>   | GSM    | Yes                             | G_0B.09.3AR_A                 | 2005 <sup>7</sup> |
|                    | i880                  | Nextel | No                              | R6E.00.01                     | 2007              |
|                    | i870                  | Nextel | No                              | R5B.00.04                     | 2007              |
|                    | i580                  | Nextel | No                              | R5C.00.01                     | 2007              |
|                    | i605                  | Nextel | No                              | R2F.00.00                     | 2007              |
|                    | V60 <sup>1,2,11</sup> | all    | Yes                             | -                             | 2005              |
| <b>LG</b>          | VX8550 Chocolate      | CDMA   | Yes                             | VX855V01                      | 2008              |
|                    | AX355                 | CDMA   | No                              | T35ATV01                      | 2007              |
|                    | AX8600                | CDMA   | Yes                             | T86ATV06                      | 2007              |
|                    | VX8600                | CDMA   | Yes                             | T86VZV02                      | 2007              |
|                    | VX8700                | CDMA   | Yes                             | T87VZB03                      | 2007              |
|                    | VX9400                | CDMA   | Yes                             | T94VZB01                      | 2007              |
|                    | VX8100                | CDMA   | No                              | T81VZ07                       | 2007              |
|                    | VX8300                | CDMA   | Yes                             | T83VZV02                      | 2007              |
|                    | VX8500 Chocolate      | CDMA   | Yes                             | T85VZB02                      | 2007              |
| <b>Nokia</b>       | 6555                  | GSM    | Yes                             | V 03.31                       | 2008              |
|                    | 6820                  | GSM    | No                              | V04.46                        | 2005              |
|                    | 6230                  | GSM    | Yes                             | V05.24                        | 2005 <sup>6</sup> |
| <b>Palm</b>        | Treo 650              | GSM    | "Favorites" only                | 1.13 <sup>5</sup>             | 2006              |
|                    | Treo 680              | GSM    | "Favorites" only                | 1.31                          | 2007              |
|                    | Treo 700p             | CDMA   | "Favorites" only                | 1.42/32/142                   | 2007              |
|                    | Treo 700wx            | CDMA   | "Favorites" only                | 1.11-ROWEN                    | 2007              |

# Audi Phone Preparation with Bluetooth® Compatible Cell Phones by Manufacturer

|                           |                     |      |                   |           |                   |
|---------------------------|---------------------|------|-------------------|-----------|-------------------|
| <b>Research In Motion</b> | BlackBerry 8100     | GSM  | Yes <sup>12</sup> | V4.2.0.51 | 2008              |
|                           | BlackBerry 8300     | GSM  | Yes <sup>12</sup> | V4.2.2.30 | 2008              |
|                           | BlackBerry 8800     | GSM  | Yes <sup>12</sup> | 4.2.1.72  | 2008              |
|                           | BlackBerry 7100     | GSM  | No                | 4.0.0.198 | 2006              |
|                           | BlackBerry 7130e    | CDMA | No                | V4.1      | 2007              |
|                           | BlackBerry 7290     | GSM  | No                | 4.0.0.198 | 2006              |
|                           | BlackBerry 8703e    | CDMA | No                | v4.10.373 | 2007              |
|                           | BlackBerry 8830     | CDMA | Yes <sup>12</sup> | 4.2.2.66  | 2008              |
| <b>Sanyo</b>              | SCP-8500 Katana DLX | CDMA | Yes               | 1.002SP   | 2008              |
|                           | SCP-6600 Katana     | CDMA | Yes               | 1.000SP   | 2007              |
|                           | SCP-8400            | CDMA | Yes               | 1.002SP   | 2007              |
|                           | SCP-7050            | CDMA | Yes               | 1.002SP   | 2007              |
|                           | M1                  | CDMA | Yes               | 1.001SP   | 2007              |
| <b>Samsung</b>            | M510                | CDMA | Yes               | AC19      | 2007              |
|                           | M620 UpStage        | CDMA | Yes               | AC08      | 2007              |
|                           | M610                | CDMA | Yes               | ZJ29      | 2007              |
|                           | A900M               | CDMA | Yes               | ZJ23      | 2007              |
|                           | M500                | CDMA | Yes               | ZK03      | 2007              |
|                           | A960                | CDMA | Yes               | ZA09      | 2007              |
|                           | A900                | CDMA | Yes               | ZD12      | 2007              |
|                           | A940                | CDMA | Yes               | ZA13      | 2007              |
|                           | U420                | CDMA | No                | ZF29      | 2007              |
| <b>Siemens</b>            | S56                 | GSM  | Yes               | 20        | 2005              |
|                           | S66                 | GSM  | Yes               | 48        | 2005 <sup>6</sup> |
| <b>Sony Ericsson</b>      | T610 <sup>10</sup>  | GSM  | Yes               | R3A       | 2005 <sup>6</sup> |
|                           | T616 <sup>10</sup>  | GSM  | Yes               | R1B       | 2005              |
|                           | T630 <sup>10</sup>  | GSM  | Yes               | R3C       | 2005 <sup>6</sup> |
|                           | T637 <sup>10</sup>  | GSM  | Yes               | R5A       | 2006              |
|                           | T637 <sup>10</sup>  | GSM  | Yes               | R3A       | 2005 <sup>6</sup> |
|                           | W300i               | GSM  | Yes               | R4EA031   | 2007              |
|                           | W810i               | GSM  | Yes               | R4EA031   | 2007              |
|                           | Z525i               | GSM  | Yes               | R3K028    | 2007              |

Phones listed above have been tested for compatibility with the Audi Phone Preparation. Other Bluetooth®-equipped phones may have various levels of compatibility with Audi vehicles, but are not supported by Audi.

**Major GSM carriers: AT&T and T-Mobile. Major CDMA carriers: Alltel, Sprint and Verizon.**

\* Older phone cradles (for vehicles equipped with Audi Telematics by OnStar®) will not function in combination with the new Audi Phone Preparation. Please use the new cradle part numbers listed on this sheet.

- 1 These phones are not Bluetooth®-equipped, but will work with the Audi Phone Preparation in conjunction with the appropriate phone cradle.
- 2 V60 "street" phones will not work; only Audi OEM Versions sold through an Audi dealer are compatible.
- 3 CDMA phones: numbers stored in the phonebook are synchronized with the vehicle.  
GSM phones: numbers stored in the phonebook and the SIM-card are synchronized, except where noted.
- 4 Older phone firmware may not be fully compatible and may cause system instability; contact your phone provider to be sure the latest firmware is loaded in your phone.
- 5 Minimum v1.15 for AT&T version. Software downloads available at [www.palm.com](http://www.palm.com)
- 6 MY2005 A8 models without Audi Telematics by OnStar® equipment are compatible.  
MY2005 A6 models after VIN: 4F\_070061 are compatible.
- 7 Audi strongly recommends the use of the Audi phone cradle for optimum performance in MY2005 vehicles.
- 8 Audi phone cradle available, part number - 4F0 051 435 B
- 9 Audi phone cradle available, part number - 4F0 051 435 C
- 10 Audi phone cradle available, part number - 4F0 051 435 D
- 11 Audi phone cradle available, part number - 4F0 051 435 E
- 12 Dialed, Missed, and Received call lists downloaded from phone are inaccurate
- 13 A sporadic Bluetooth link disconnect may be experienced on some vehicles.

For optimal audio quality disable Wi-Fi on phone. A short noise may sporadically occur when calls first initiated.

Limitations dialing International numbers from memory. Silent ringer should not be used in MY07 vehicles.

Audi of America, Inc. and Audi Canada believe the information presented to be correct at the time of publication. All specifications are subject to revision. Check the [www.audiusa.com](http://www.audiusa.com) or [www.audicanada.ca](http://www.audicanada.ca) websites regularly for updates to this matrix. Bluetooth® is a registered trademark of the Bluetooth SIG, Inc.. OnStar® is a registered trademark of OnStar Corporation.

Rev. 10/15/2007